

Wykaz norm

AIEE and ASA standards are not available in the AGH Library Catalogue (cannot be ordered electronically). As at September 2026.	
Normy AIEE i ASA niedostępne w Katalogu Bibliotek AGH (brak możliwości zamówienia elektronicznego). Stan na wrzesień 2026 r.	
numer normy / standard number	nr inwentarza / inventory number
AIEE-1:1954	20582/NZ
AIEE-16:1955=ASA C48.1:1955	20630/NZ
AIEE-17f:1928=ASA Z10.F:1928	20631/NZ
AIEE-18:1951=ASA C55.1:1951	20632/NZ
AIEE-1A:1941	20625/NZ
AIEE-1B:1944	20626/NZ
AIEE-1C:1954	20627/NZ
AIEE-21:1943=ASA C76.1:1943	20633/NZ
AIEE-22:1952	20634/NZ
AIEE-25:1952	20635/NZ
AIEE-27:1955=ASA C37.20:1955	20636/NZ
AIEE-28B:1956	20638/NZ
AIEE-29:1943= ASA C77.1:1943	20638/NZ
AIEE-3:1943	20628/NZ
AIEE-30:1953=ASA C8.1:1944	20639/NZ
AIEE-31:1944	20640/NZ
AIEE-32:1947	20641/NZ
AIEE-4:1953= ASA C68.1:1953	20629/NZ
AIEE-43:1950	20642/NZ
AIEE-45:1955	20643/NZ
AIEE-450:1955	20656/NZ
AIEE-451:1955	20657/NZ
AIEE-452:1955	20658/NZ
AIEE-48:1948	20644/NZ
AIEE-49:1948	20645/NZ
AIEE-50:1953	20646/NZ
AIEE-501:1941	20659/NZ
AIEE-503:1945	20660/NZ
AIEE-504:1953	20661/NZ
AIEE-505:1955	20662/NZ
AIEE-506:1955	20663/NZ
AIEE-51:1955	20647/NZ
AIEE-52:1951	20648/NZ
AIEE-53:1952	20649/NZ
AIEE-54:1955	20650/NZ
AIEE-55:1953	20651/NZ

Wykaz norm

AIEE-550:1949	20664/NZ
AIEE-551:1950	20665/NZ
AIEE-552:1955=ASME PTC 19.6:1955	20666/NZ
AIEE-56:1954	20652/NZ
AIEE-57:1955	20653/NZ
AIEE-58:1956	20654/NZ
AIEE-59:1956	20655/NZ
AIEE-600:1949	20667/NZ
AIEE-601-and-602:1953=ASME 100:1953	20668/NZ
AIEE-605:1950	20669/NZ
AIEE-700:1953	20670/NZ
AIEE-800:1953	20671/NZ
AIEE-801:1954	20672/NZ
AIEE-802:1955	20673/NZ
AIEE-950:1952	20674/NZ
AIEE-952:1956	20675/NZ
AIEE-953:1956	20676/NZ
AIEE-954:1954	20677/NZ
AIEE-955:1955	20678/NZ
ASA-C34-1:1949	20686/NZ
ASA-C37-1:1950	20687/NZ
ASA-C37-12:1952	20696/NZ
ASA-C37-13:1954	20697/NZ
ASA-C37-14:1954	20698/NZ
ASA-C37-15:1954	20699/NZ
ASA-C37-2:1945	20688/NZ
ASA-C37-4:1953	20689/NZ
ASA-C37-4a:1954-C57-12b:1954	20690/NZ
ASA-C37-5:1953	20691/NZ
ASA-C37-6:1955	20692/NZ
ASA-C37-7:1952	20693/NZ
ASA-C37-8:1952	20694/NZ
ASA-C37-9:1953	20695/NZ
ASA-C39-1:1955	20700/NZ
ASA-C39-2:1953	20701/NZ
ASA-C50-1:1955	20702/NZ
ASA-C50-2:1955	20703/NZ
ASA-C50-20:1954	20707/NZ
ASA-C50-4:1955	20704/NZ
ASA-C50-5:1955	20705/NZ
ASA-C50-6:1955	20706/NZ
ASA-C57-10:1953	20708/NZ
ASA-C57-11:1953	20709/NZ
ASA-C57-12:1949	20710/NZ
ASA-C57-12-section-30:1956	20711/NZ
ASA-C57-12a:1954	20712/NZ
ASA-C57-13:1954	20713/NZ

Wykaz norm

ASA-C57-15:1949	20714/NZ
ASA-C57-25:1949	20715/NZ
ASA-C57-33:1953	20716/NZ
ASA-C8-18:1948	20684/NZ
ASA-C8-19:1939	20685/NZ
ASA-Y32-2:1954	20679/NZ
ASA-Y32-9:1943	20680/NZ
ASA-Z10-5:1949	20681/NZ
ASA-Z24-7:1950	20682/NZ
ASA-Z32-13:1950	20683/NZ